

Appendix 14-7- Plates from Field Walkover Survey, 2023.



14.7 PLATES FROM FIELD WALKOVER SURVEY, 2023



View of area in the S of Derryaroge bog.



View of area overgrown in townland of Cloonfore in S of Derryaroge bog.



View of location of Turbine 2, from the N.



View of area in the east of the townland of Mount Davys



View of internal railway along the line of the internal access road / amenity track, that exits the bog in the townland of Mountdavis



View of internal access road between Turbine 1 and Turbine 3, taken from the S.



View of Turbine 3



A proposed construction compound located in an area of cutaway bog and partly overgrown.



View of amenity road that exits Derryaroge Bog in the NE.



View of amenity road that runs from Turbine 5, taken from the N.



View of location of Turbine 5



General View of the internal access road between Turbine 5 and Turbine 6, taken from the N.



General view of internal access road in between Turbine 5 and Turbine 4, taken from the E.



View of internal access road in the NW of Derryaroge bog



General view of internal access road to the N of Turbine 4.



View of location of Turbine 3



View of access road between Turbine 3 and Turbine 4.



View of area of Turbine 7



View of location of Turbine 6



General view of internal access road from Turbine 7 to the area of the substation in the SE of Derryaroge bog.



Area of proposed substation and peat repository in the SE of Derryaroge bog.



View of area of internal access road and grid connection from Derryad Bog towards Derryaroge Bog.



View of area of construction compound to the E of Mountdillon Office Works.



View of are of Construction Compound



View of railway tracks to the SE of Moundillon Office works



View of proposed internal access road towards turbine 8, taken from the N.



View of location of turbine 8.



View of internal access road running S from turbine 8.



View of location of turbine 9



General view of overgrown area between turbine 8 and turbine 9.



View of location of turbine 10



General view of overgrown area of Borrow Pit No.1.



View of location of turbine 13.



View of location of borrow pit No. 2 from the north.



View of location of Turbine 14.



View of location of Turbine 15



View of location of turbine 12



View of internal access road between turbine 11 and 12



View of location of Borrow pit No. 3



View of location of borrow pit No. 4



View of location of turbine 11



View of proposed N-S running internal access road in the S of Derryad bog



View of cutaway bog and peat depths along N-S running internal access road in Derryad bog.

Lough Bannow bog



View of internal access road north of Derryglogher House



View of internal access road that runs adjacent to west boundary in lough Bannow Bog.



View of internal access road that runs north south towards turbines 16 and 17.



View of location of turbine 16.



View of location of turbine 17.



View of location of turbine 18



View of location of turbine 19.



View of amenity road in townland of Corlea



View of amenity road towards turbine 21



View of location of turbine 21



General view of internal access road between turbine 21 and turbine 22.



View of amenity road



View of location of turbine 20.



View of location of turbine 22



General view of cutaway bog and area overgrown with vegetation, between turbine 22 and turbine 21.



General view of area overgrown with vegetation, between turbine 22 and turbine 21.